



Manual 说明书



ON/OFF — Mode button
Input Port



3 MODE WINDING

Mode 1



1档：顺时针转动6分钟停30分钟。

Clockwise rotation for 6 minutes and stop for 30 minutes.

Mode 2



2档：逆时针转动6分钟停30分钟。

Counter-clockwise rotation for 6 minutes and stop for 30 minutes.

Mode 3



3档：顺时针转动4分钟逆时针转动4分钟停26分钟。

Clockwise rotation for 4 minutes then counter-clockwise rotation for 4 minutes and stop for 26 minutes.